



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**



REGISTERED MAIL and EMAIL

Samet İkikardes
General Manager
Ekol Glass Cam Sanayi Ve Ticaret Limited Sirketi
Vakif Mah. 9. Turan Sk. No:1/A
16300 YILDIRIM / BURSA
TURKEY

Dear Samet İkikardes:

This is in reply to your recent request for assignment of a glazing material manufacturer's identification code for the Ekol Glass Cam Sanayi Ve Ticaret Limited Sirketi plant located in Bursa, Turkey.

We are assigning the four number code “**1351**” for this plant. Our records show the address of the main office and plant address as follows:

Plant

Ekol Glass Cam Sanayi Ve Ticaret Limited Sirketi
Vakif Mah. 9. Turan Sk. No:1/A
16300 YILDIRIM / BURSA
TURKEY

Main Office

Ekol Glass Cam Sanayi Ve Ticaret Limited Sirketi
Vakif Mah. 9. Turan Sk. No:1/A
16300 YILDIRIM / BURSA
TURKEY

The use of the DOT symbol molded into or onto glazing material constitutes a certification by the manufacturer that the glazing material meets applicable Federal safety requirements. To provide a basis for its certification of compliance, a prime glazing manufacturer may choose any valid means of evaluating its procedures to determine whether the glazing complies with FMVSS No. 205 (e.g., through actual testing, computer simulation, engineering analyses, or other means). However, the manufacturer must ensure that the product will meet FMVSS No. 205 when tested by NHTSA using the test procedures and conditions specified in the standard. Further, NHTSA may require a manufacturer to provide the data it used to determine whether the glazing material met FMVSS No. 205 requirements.

In addition, a manufacturer is subject to civil penalties up to \$27,874 per item but not to exceed \$139,356,994 under 49 U.S.C. Chapter 301, unless it can establish that it had no reason to know, despite exercising reasonable care, that the equipment did not comply.

The glazing material manufacturer's identification code mark is required on all regulated glazing material sold in the United States for highway use. This code mark and other glazing material identification labeling are specified in the glazing material standard.

Should you no longer need an ID code mark or if any one of the following events occur, please notify us immediately, including the date of the change and the month, day and year the last glazing materials were produced using the codes in question so that our records can be updated:

1. There is a change in company or plant name or address.
2. The company or plant is closed.
3. The company or plant is sold or merged with another company.
4. There is a change in the types of glazing materials manufactured at each plant.

On any future correspondence concerning a glazing material plant or the parent glazing material company, please reference the glazing material plant ID code(s) involved. If you have any further questions, please contact Patrice Moore at (202) 366-5317 or DOTPlantCodeApplication@dot.gov.

Sincerely,

Claudia Covell
Chief, Equipment Division
Office of Vehicle Safety Compliance

cc: Amanda Mallory
217 Cherokee Dr.
Simpsonville, SC 29680